INTERFERENCE SEARCH

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L38	1	(weld$3 and fixture and sensor with cover and spring and perpendicular and weight).clm.	US-PGPUB	OR	ON	2006/03/27 14:49
L39	1	(weld$3 and fixture and SAW and sensor and spring and perpendicular and weight).clm.	US-PGPUB	OR	ON	2006/03/27 14:50
L40	2	(weld$3 and fixture and (high or low)same power same laser).clm.	US-PGPUB	OR	ON	2006/03/27 14:51
L41	1	(weld$3 and fixture and sensor same base and stitch same weld$3).clm.	US-PGPUB	OR	ON	2006/03/27 14:52
L42	1	(weld$3 and sensor same base and located and perpendicular same laser same beam).clm.	US-PGPUB	OR	ON	2006/03/27 14:53
L43	1	(weld$3 and adjust$5 same load and foot and specific same weight).clm.	US-PGPUB	OR	ON	2006/03/27 14:55
L44	1	(weld$3 and sensor same cover same base same (via or through) and plurality same stitch and seal$3 and package).clm.	US-PGPUB	OR	ON	2006/03/27 14:56

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	79	228/103.ccls.	US-PGPUB	OR	ON	2006/03/27 14:30
L4	34	228/49.1.ccls.	US-PGPUB	OR	ON	2006/03/27 14:01
L5	4	228/49.2.ccls.	US-PGPUB	OR	ON	2006/03/27 14:31
L6	5	228/49.4.ccls.	US-PGPUB	OR	ON	2006/03/27 14:01
L7	36	228/49.5.ccls.	US-PGPUB	OR	ON	2006/03/27 14:31
L9	145	219/121.63.ccls.	US-PGPUB	OR	ON	2006/03/27 14:32
L10	223	219/121.64.ccls.	US-PGPUB	OR	ON	2006/03/27 14:33
L11	1695	219/121.6.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:39
L12	702	228/44.3.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:04
L13	785	228/212.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:04

L14	3109	11 or 12 or 13	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:05
L15	0	14 and weld$3 same fixture near50 sensor with cover same spring same perpendicular same weight	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:48
L16	1	14 and weld$3 and fixture and sensor same cover and spring and perpendicular and weight	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:09
L17	0	14 and load same bar` same perpendicular and weight	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:09
L18	1	14 and load same bar and perpendicular and weight	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:10

L19	3	228/103.ccls. and load same bar and perpendicular and spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:13
L20	2	"20050194362"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:13
L21	1	20 and perpendicular and spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:37
L22	1	20 and load same bar and receiv$3 and spring and perpendicular	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:15
L23	1	14 and weld$3 same load same bar and sensor near50 base same spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:28

EAST Search History

L24	1	14 and weld$3 same load same bar and sensor same spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:28
L25	1	14 and weld$3 same bar and sensor same spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:29
L26	1	14 and weld$3 same load same (specific or exact or predetermined) same weight same spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:30
L27	1	20 and locat$3 same pin	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:37
L28	233	219/86.1.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:44

3/27/2006 2:58:29 PM

Page 4

C:\Documents and Settings\maboagye\My Documents\EAST\Workspaces\10792247   sensor pre-load weld fixture method and apparatus

L29	0	28 and weld$3 same fixture and load same bar and spring and sensor and base	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:41
L30	1	28 and weld$3 same fixture and bar and spring and sensor and base	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:42
L31	0	28 and weld$3 same fixture and guidepost and spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:43
L32	0	28 and weld$3 same fixture and sensor and laser	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:43
L33	1	28 and weld$3 same fixture and laser	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:43

L34	385	219/158.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:44
L35	7	34 and weld$3 and (fixture or hold$3) and spring and laser	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:47
L36	0	34 and weld$3 and (fixture or hold$3) and spring and laser and bar and sensor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/27 14:47
L37	0	(weld$3 same fixture near50 sensor with cover same spring same perpendicular same weight).clm.	US-PGPUB	OR	ON	2006/03/27 14:49